IMPORTANT Service INFORMATION

DeSoto

DATE	NUMBER
1-6-60	1117

GROUP: Air Conditioning

SUB-GROUP: Tube Leaks

• SERVICE DEPARTMENT • DE SOTO DIVISION • CHRYSLER CORPORATION •

TO ALL DE SOTO DEALERS:

SUBJECT: AIR CONDITIONING TUBE SEALING WASHER REPLACEMENT PACKAGE - PART NO. 2196341

When assembling air conditioning components, there may, in some instances, be difficulty in eliminating refrigerant leaks at tubing connections where there are steel to steel or steel to brass connections. In an effort to minimize the possibility of such leaks, a package containing a sufficient quantity of copper sealing washers for all tubing connections, of either the single or the dual air conditioning system, has been released for service.

The soft copper washers contained in the new package are compressible, providing a more satisfactory seal, and tend to prevent damage to the mating surfaces of tubing connections. Therefore, should you experience difficulty in correcting refrigerant leaks at air conditioning line tubing connections, it is recommended that the washers supplied in Air Conditioning Tube Sealing Washer Replacement Package, Part No. 2196341, be used.

The part listed in this bulletin is stock code class "P".

George J. Cutler

GEORGE J. CUTLER
Director of Service
PLYMOUTH-DE SOTO-VALIANT DIVISION

P-4932-C

(THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS)

85-515-6130 DESIGNED TO ENDURE