IMPORTANT Service INFORMATION

DeSoto

DATE	NUMBER
10-28-59	1093-A

GROUP: Cooling

SUB-GROUP: Antifreeze

• SERVICE DEPARTMENT • DE SOTO DIVISION • CHRYSLER CORPORATION •

TO ALL DE SOTO DEALERS:

SUBJECT: ANTIFREEZE PROTECTION - 1960 DE SOTO CARS

This bulletin replaces De Soto Service Information Bulletin No. 1093 dated October 14, 1959. Please discard Bulletin No. 1093 and insert Bulletin No. 1093-A in its place.

This bulletin cancels and supersedes all previous De Soto Service Bulletins covering effective dates on factory antifreeze protection.

Beginning September 15, 1959 through April 30, 1960 all De Soto cars built will have the cooling system protected to - 15° F. by a permanent type Ethylene-Glycol antifreeze solution.

In order to avoid any possible damage to new cars in your stock, in the event of a severe temperature drop, it is strongly recommended that the coolant in every new De Soto received, which was built between the above dates, be tested for the strength of the antifreeze solution. The Ethylene-Glycol base antifreeze solution used can be tested on most standard antifreeze hydrometers.

Should it be found that antifreeze protection is inadequate for the anticipated temperatures in your particular area, MoPar Permanent Type Antifreeze, Part No. 1316208 in quart cans, Part No. 1316209 in gallon cans, or any reputable brand of Ethylene-Glycol base antifreeze can be added.

It is important that this information be reviewed with your service personnel who are responsible for receipt and storage of new cars.

Effective May 1, 1960, De Soto cars with factory installed air conditioning will contain antifreeze protection to + 15° F.

George J. Cutler

GEORGE J. CUTLER
Director of Service
PLYMOUTH- DE SOTO-VALIANT DIVISION

P-3777-C

(THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS)