

CHRYSLER CORPORATION

CHRYSLER DIVISION
12200 E. JEFFERSON AVE.
DETROIT 31, MICHIGAN

SERVICE BULLETIN

Service Mgr. Shop Foreman Parts Mgr. Mechanics



No. 934-CH

Date 11-10-55

TO ALL CHRYSLER DIRECT DEALERS:

When servicing an Imperial prior to the subject serial number, it is suggested that a check be made of the rear spring plates.

The shock absorber mounting eye on the spring plates of the Imperial should be turned down. It is possible that a few plates with the eyes turned up were installed on early production cars.

The installation of incorrect rear spring plates will cause the rear spring shackle to kick forward and toggle whenever the shock absorbers are extended and will also cause "bottoming" of the rear shock absorbers.

If incorrect rear spring plates are found, it will be necessary to install the correct spring plates, Part Number 1617022-3.

A handwritten signature in cursive script that reads "R. B. Teiper".

R. B. TEIPER
Director of Service
CHRYSLER DIVISION

SPRINGS

AND SHOCK

ABSORBERS

REAR

SPRING

PLATES

IMPERIAL

ALL 1956 UP

TO SERIAL

NO. C56-1526

4493

"IMPORTANT: This bulletin contains valuable information and was prepared at considerable expense to be of service to you. Failure to use this information may cost you good will and money. We suggest that you insure it is read by all those concerned, and then filed for future reference in your Service Bulletin binder."

CHRYSLER CORPORATION

CHRYSLER DIVISION
12200 E. JEFFERSON AVE.
DETROIT 31, MICHIGAN

SERVICE BULLETIN

Service Mgr. Shop Foreman Parts Mgr. Mechanics



March 26, 1956

No. 958-CH

TO ALL CHRYSLER DIRECT DEALERS:

Conditions may arise, due to overloading, operating conditions, etc., where it may become desirable to reinforce rear springs to maintain proper vehicle height. In these situations it is much more desirable to reinforce the springs already in the car than to install similar new springs. Therefore, a rear spring service package Part No. 1731728 has been released. These are available from your regular MoPar parts source and consist of the following:

- 2 - Spring Leaves
- 2 - Inner-liners
- 2 - Center Bolts and Nuts
- 6 - Clips
- 6 - Screws, Washers and Nuts

To install this reinforcement package, remove and disassemble the rear springs. Install the extra spring leaf, with inner-liner on top, directly beneath the rear spring main leaf and reassemble using the new center bolts, clips, etc.

As this is a new operation the following Service Operation Time Schedule is given:

17-280 Install rear spring reinforcement leaves.

One side - 1.6
Both sides - 3.0

A handwritten signature in cursive script.

R. B. TEIPER
Director of Service
CHRYSLER DIVISION

SPRINGS

REAR

SPRING

SERVICE

PACKAGE

CHRYSLER

1955 & 1956

C67, C68, C71

& C72 WINDSOR

& NEW YORKER

MODELS

8756

PRINTED IN U.S.A.

"IMPORTANT: This bulletin contains valuable information and was prepared at considerable expense to be of service to you. Failure to use this information may cost you good will and money. We suggest that you insure it is read by all those concerned, and then filed for future reference in your Service Bulletin binder."