



# Technical Service Bulletin

DATE May 10, 1967

NUMBER 67DT-12 MODEL 1961-1966 MODEL D100-600, C500-600, S400-600

GROUP PROPELLER SHAFT SUBJECT IMPROVED PROPELLER SHAFT CENTER BEARING KIT

SUMMARY SLINGER TYPE CENTER BEARING REDUCES BEARING CONTAMINATION FROM ROAD SPLASH.

This bulletin supersedes Truck Technical Service Bulletin 66DT-49 and introduces a kit which includes all of the individual pieces shown in 66DT-49.

Under certain operating conditions it is possible that extensive road splash may reduce normal life of the propeller shaft center bearing. This road splash may cause rapid wear of the bearing seal resulting in dirt contamination and bearing seizure.

Kit P/N 3004542 is now available from MoPar and is stock class Code "M".

Policy: Information only.

A handwritten signature in black ink, appearing to read "R. H. Kline".

R. H. KLINE  
Manager - Service  
DODGE DIVISION