

SERVICE BULLETIN



SERVICE DEPARTMENT
DODGE
DIVISION OF CHRYSLER CORPORATION

TO ALL DIRECT DEALERS AND DEALERS:

The horn blowing ring of the model D22 Dodge car is held in place by a retainer which contacts the ring at four points.

However, it has been found, in some cases, that the ring did not contact the retainer properly, and it would rock and rattle.

In such cases, it is suggested that the ring be removed and the short projection which extends out from the hub directly opposite the short spoke be cut off as near to the hub as possible.

Enter this bulletin number and subject in your Dodge Passenger Car Shop Manual under Group - Electrical.

B. B. SETTLE
Director of Service
DODGE DIVISION

Dec. 10, 1941

No. D-105

ELECTRICAL

--

HORN BLOWING

RING RATTLES

--

MODEL: D22

6394

Prtd. in U.S.A.

14783