

SERVICE BULLETIN



SERVICE DEPARTMENT
DODGE
DIVISION OF CHRYSLER CORPORATION

Nov. 8, 1945

No. D-134

TO ALL DIRECT DEALERS AND DEALERS:

The oil pumps of all trucks and some service engines built since last January have been fastened to the cylinder block with round head screws which have a hexagon shaped hole in the head.

To tighten these screws an L-shaped tool similar to an Allen Wrench is necessary. However, the usual Allen Wrench is not suitable as the side of the "L," which is inserted in the hole, is too long and the handle is so short that the screws cannot be tightened sufficiently to prevent oil leakage.

A special wrench has, therefore, been made available and can be obtained by ordering #C-729 Wrench, oil pump Allen Cap Screw from the Miller Manufacturing Company, 1725 Sixteenth Street, Detroit 16, Michigan. The price is \$1.00 net.

Enter this bulletin number and subject in your shop manuals - Group Engine.

ENGINE

OIL PUMP

ALLEN CAP SCREW

WRENCH

B. B. SETTLE
Director of Service
DODGE DIVISION